Originating Office:
AIR-130

Document Description:TSO-C159c
Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
Date of Review:

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
1.	Garmin	Page 2-3, Paragraph 3.a	Table 1B and Table 2B Requirements column refer to Appendix E Sections 2.2.1.1.X that do not exist in DO-262B as numbered sections. It appears that the intention of DO- 262B Appendix E was to include sections 2.2.1.1.1 to 2.2.1.1.11 as it refers to these sections in paragraph 2.2.1.1. If Table 2B keeps the references to 2.2.1.1.X, then all of the "X" values should be reduced by 1 to keep the subparagraph numbered logically. The range would be 2.2.1.1.4 to 2.2.1.1.11 instead of the shown 2.2.1.1.5 to 2.2.1.1.12.	Update all references to Appendix E, Section 2.2.1.1.	Concur. DO-262B Appendix E appears to have an editorial error in which the referenced subparagraphs are missing their numerical designators. The Appendix E references in the TSO were revised to indicate the applicable subparagraph titles within DO-262B Appendix E section 2.2.1.1.
2.	Garmin	3.c.(1-3) Page 4	Paragraph. 3.c.(3) includes the statement: Develop the system to, at least, the design assurance level equal to this failure condition classification.	Suggest changing to the alternate wording identified in paragraph 3.c. of the TSO Template in Order 8150.1C Appendix G.	Nonconcur for the following reasons: 1) Failure condition classifications identified in paragraph 3.c refer to the effect of the loss

Originating Office:
AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
David W. Robinson

Commenter	Section # and Page #	Comment	Suggested Change and Rationale		Disposition
		Wording needs to change to allow			or failure of function
		failure condition to be determined at the			on the aircraft (i.e.,
		aircraft level.			at the <i>aircraft</i> level)
					consistent with the
		This statement implies the failure			definition of "failure
		condition classification of an appliance			condition" and
		is determined by the TSO regardless of			associated failure
		mitigations employed to meet aircraft			condition
		level safety requirements such as			classification
		redundant appliances/systems. Unless			definitions provided
		the DAL cannot be affected by the			in AC XX.1309.
		installation, the aircraft System Safety		2)	Per the functionality
		Assessment should determine the			definition in
		failure classification and by extension,			paragraph 3.b, the
		the design assurance level (DAL)			failure condition
		requirement. The aircraft FHA/SSA			classifications
		ultimately determines the DAL			identified in
		requirement for a particular installation.			paragraph 3.c are
		Specifying the DAL at the appliance			based on the two
		level without the benefit of the specific			safety related
		aircraft level FHA/SSA means that in			functions (ATS and
		some cases the DAL will undoubtedly			AOC). That being
		be higher and more costly than			said, note that the
		necessary. This will have a chilling			effect of loss or
		effect on the installation of new, safety			failure of function is
		enhancing technologies since the cost			only identified as
		will be greater than necessary. It is			minor. The FAA

Originating Office:
AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
Date of Review:

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
			possible to build and certify a TSOA appliance that cannot be approved for installation in one or more aircraft types because it does not have the required DAL. Similarly, just because the appliance meets a TSO DAL does not mean it can be approved for installation. We recommend that no failure classification/DAL requirement be included in a TSO when the installation can affect or mitigate the hazard level and therefore consideration should be given to revising paragraph 3.c in this TSO to the general guidance in the Recommendation column. Additionally 2 of the 4 communication categories supported by this TSO are listed as non-safety of flight functions in 3.b. For systems that only support these 2 communication categories the DALs listed in the TSO are inconsistent.		would not consider equipment designed only to support the other two functions (AAC and APC) as significantly safety-enhancing.
3.	Garmin	3.g Page 5	Including this specific DO-254 reference is redundant to the rest of the paragraph in this section.	Remove this reference to DO-254 Paragraph 1.6.	Comment no longer applicable. We have rewritten paragraph 3.c to state that loss or failure of

Originating Office: AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Document Description:TSO-C159c
Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
Date of Review:

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
			For custom airborne electronic hardware determined to be simple, RTCA/DO-254, paragraph 1.6 applies. DO-254 makes it clear how to address "simple" custom airborne electronic hardware.		function is a minor failure condition, based on NGSS being supplemental to HF communications. Accordingly, per policy, paragraph 3.g is no longer required and we have deleted it from this revision of the TSO.
4.	Garmin	4.b Page 5	TSO paragraph 4.b includes the statement: Also, mark the following permanently and legibly, with at least the manufacturer's name, subassembly part number, the TSO number, class and subclass identification: The Order 8150.1C TSO template does not include the "equipment class and subclass" phrase.	Remove "class and subclass identification" from paragraph 4.b. Garmin is routinely granted deviations from TSO requirements to mark the "applicable equipment class(es)" as the equipment does not have sufficient space to include this as well as all other required markings (e.g., multiple TSOs and SW level, etc. that appear in other TSOs). This deviation is granted through	Nonconcur. This TSO equipment marking is not a template requirement but made at the request of manufacturers to increase flexibility of component TSO product development. The discussion of marking size/space was not an issue and was desirable to those equipment manufactures involved.

Originating Office:
AIR-130

Document Description:TSO-C159c
Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
Date of Review:

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
				use of a marking similar to the example in Order 8150.1C ¶ 7-4.e.(4).(b) "See Inst Mnl for Addtl TSO approvals and/or markings.".	
5.	Garmin	4.b.(2) Page 5	Paragraph 4.b.(2) states: Each subassembly of the article that you determined may be interchangeable. This language is confusing.	The language for this requirement is confusing. This could mean that a stuffed printed circuit board needs the TSO number. Suggest removing the statement or if removing causes problems, work with industry to establish wording that is better understood.	Nonconcur. This wording is consistent with TSO template. This statement refers to Table 3, Valid Combinations of System Components, where some components are interchangeable with each other within the same Class.
6.	Garmin	5.e Page 8	TSO paragraph 5.e and its subparagraphs include definition of non-TSO functions and the data to be submitted to the ACO for non-TSO functions. This guidance is inconsistent with Order 8110.4C CHG 4.	TSO paragraph 5.e states "Identify functionality or performance contained in the article not evaluated under paragraph 3 of this TSO (that is, non-TSO functions)." Use of the term "performance" in the definition of a non-TSO function is inconsistent with the Order 8110.4C CHG 4	Nonconcur. Order 8110.4C (Chg 5 incorporated) para 6-9.b.(1) defines a non-TSO function as "one that is not covered by a TSO-approved minimum performance standard (MPS), does not support or affect the hosting article's TSO function(s), and could technically be implemented outside of the

Originating Office:
AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
Date of Review:

	Section #		Suggested Change	
Commenter	and	Comment	and	Disposition
	Page #		Rationale	
			paragraph 6-9.b.(1) and 6-	TSO article." Furthermore,
			9.b.(3)(a) guidance regarding	Para 6.9.b.(3)(b) of the order
			how to define a non-TSO	requires manufacturers to
			function. The issue is non-	submit the manufacturer's
			TSO should not be defined	declared performance
			as "performance". It will	requirements for the non-
			create difficulty if these	TSO function(s). It is these
			criteria are used. For	aspects of "functionality or
			example, if a TSO requires a	performance" that the TSO
			minimum 10 watt transmitter	template language refers to
			and a company makes	here. In the example the
			equipment that is robust at	commenter gives, as the
			11 watts, the performance	commenter identifies, an 11-
			exceeding the TSO is not	watt transmitter that must
			called out under the TSO;	output a minimum of 10
			consequently, by the	watts does not have 1 watt
			paragraph 5.f "performance"	of "non-TSO function",
			definition, the 11 watt	since transmitter power is
			transmitter has a non-TSO 1	covered by the MPS and
			watt capability. The	since that extra watt cannot
			distinction of a "function that	be implemented outside the
			can be accomplished outside	TSO article. Rather, it
			the TSO box" as is specified	simply meets the TSO
			in Order 8110.4C CHG 4	minimum performance
			paragraph 6-9 is critical to	standard, with a 1-watt
			making non-TSO function	margin above the minimum.
			work long term.	As such, we do not view the

Originating Office:
AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Project Lead/Reviewer
David W. Robinson

David W. Robinson

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
				Adjust the wording in the TSO (and template) to be consistent with the 8110.4C CHG 4 intent.	referenced template language as inconsistent with Order 8110.4C requirements. No change necessary.
7.	Garmin	7.b. Page 10	TSO paragraph 7.b contains wording that is inconsistent with Order 8110.4C CHG 4.	TSO paragraph 7.b includes additional guidance about what furnished data should be provided to an operator or repair station when the equipment includes a non-TSO function. The problematic guidance states "include one copy of the data in paragraphs 5.e.(1) through 5.e.(4)." This guidance is inconsistent with Order 8110.4C CHG 4. Order 8110.4C CHG 4 paragraph 6-9.b.(6) defines the FAA-industry agreed data that must be provided to an installer when equipment includes a non-TSO function.	Nonconcur. We have examined the referenced TSO template language against the requirements of Order 8110.4C (Chg 5 incorporated), para 6.9.(b)(6), and although the template language is not a word-for-word match to the order, we find it consistent with the data requirements specified in that paragraph of the order. Refer to paragraph 6.9.(b)(6)(a),(b),(c) of the order for comparison. Any further concerns with non-TSO function data should be discussed with the ACO at project initiation. No

Originating Office:
AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
David W. Robinson

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
					change necessary.
8.	AIRBUS	Section 3 Note Page 1	The Note is misleading and even not relevant: 1) Indeed, the section 3 clearly states that RTCA/DO-326 or RTCA/DO-326A (Airworthiness Security Process Specification) are not applicable, that means that no security risk assessment is required to the TSO applicant. 2) The Note states that a security risk assessment may be required at the time of installation, ie. to be carried out by the TC holder or a STC applicant when the TC holder or a STC applicant installs the equipment. Because it is part of a certification activity (TC, change to TC, STC), such considerations given in the note are out of the TSO scope 3) The FAA AIR policy statement PS-AIR-21.16-02, Establishment of Special Conditions for Cyber Security does not consider the NGNSS		Concur. We have deleted this Note from the TSO and, as necessary, will incorporate applicable guidance on cybersecurity considerations for NGSS installations into a future revision of the associated AC 20-150.

Originating Office:
AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Project Lead/Reviewer
David W. Robinson

David W. Robinson

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
	AIDDUC	Section 2	equipment as being connected to non-trusted services (or non-governmental services). Therefore, this policy statement should not be applicable to the NGNSS equipment		A. N. d. market iller Tiler
9.	AIRBUS	Section 3c Page 4	We determined the failure condition specified in paragraphs 3.c.(1) and 3.c.(2) of this TSO based on the assumption that the NGSS equipment is intended for applications that typically supplement HF voice communications in procedural airspace area operations → Does that mean that FAA understanding is that for A/C without HF and with SATCOM, SATCOM FC is still minor?		A: Not necessarily. The failure condition classification is based on the hazard class of the function considering the operating environment, Required Communication Performance (RCP) and operating procedures. The failure condition specified in paragraphs 3.c.(1) and 3.c.(2) of this TSO is based on NGSS equipment supplementing primary HF voice communications in procedural airspace area operations. We have rewritten paragraph 3.c to state that loss or failure of function is a minor failure condition, based on NGSS

Originating Office:
AIR-130

Document Description:TSO-C159c
Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
Date of Review:

	Commenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
					being supplemental to HF communications. Use of NGSS equipment for primary voice or data communications may include a need to develop the NGSS equipment to a higher design assurance level than specified in paragraphs 3.c.(1) through 3.c.(3) and drive a revision to this TSO.
10	AIRBUS	Section 3c Page 4	Use of NGSS equipment for other purposes (for example, where the equipment is required to apply the separation minimum in procedurally controlled airspace, or for some applications in high-density terminal or en route domestic airspace) may impact equipment performance and safety considerations, which may include a need to develop the NGSS equipment to a higher design assurance level than specified in paragraphs 3.c.(1) through 3.c.(3). → It is premature to provision higher DAL at this stage. Safety assessment is		Partially concur. The failure condition classification is based on the hazard class of the function considering the operating environment, Required Communication Performance (RCP) and operating procedures. The failure condition specified in paragraphs 3.c.(1) and 3.c.(2) of this TSO is based on NGSS equipment supplementing primary HF voice communications in procedural airspace area

Originating Office:
AIR-130

Next Generation Satellite Systems (NGSS)
Equipment

Project Lead/Reviewer
David W. Robinson

Reviewing Office:
Date of Review:

Co	mmenter	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
			on-going to determine the required DAL for ATN/IPS, but there is no conclusion yet.		operations. We have rewritten paragraph 3.c to state that loss or failure of function is a minor failure condition, based on NGSS being supplemental to HF communications. Use of NGSS equipment for primary voice or data communications may include a need to develop the NGSS equipment to a higher design assurance level than specified in paragraphs 3.c.(1) through 3.c.(3) and drive a revision to this TSO. With regard to the above, however, it should be noted that the original intent of this section was not necessarily to provide specifically for ATN/IPS (although ATN/IPS may also eventually be found to require a higher DAL, as the commenter notes.)

5	Document Description:TSO-C159c Next Generation Satellite Systems (NGSS)	Project Lead/Reviewer David W. Robinson	Reviewing Office:	Date of Review:
	Equipment			